



TEST CERTIFICATE

Certificate # C22107A

Client:	Cameron Moore/Jenn Pregowski MAX Interactive 130 McCormick Costa Mesa, CA 92626	Phone: (888) 799-6837 x1102 Fax: N/A Email: jenn@maxcases.com
----------------	--	---

Test Site:	Quality Testing Services 15661 Producer Lane, Unit H Huntington Beach, CA 92649	Phone: (714) 903-1155 Email: Eric@qualitytest.net
-------------------	---	--

Quote #	Verbal
Job number #	22107A
PO #	Unk
Product Tested:	Lenovo N-23 Chrome Book, Extreme Shell 2.0

Authorization	
Tom Prendergast	2-22-2018
Test Performed By	Test Date(s)
Eric Gerlach	2-22-2018
Test Certificate Author Owner	Date

Testing Performed			
Description	Specification / Paragraph	Test levels	Notes
Transit Drop Test	MIL STD 810G, Method 516.6, Paragraph 4.6.5.3, Procedure IV	Drop on each face, edge and corner for a total of 26 drops.	<p>On right face drop, some slight scuffing appeared on the upper right corner of the case.</p> <p>On bottom face drop, slight scuffing appeared on bottom right corner.</p> <p>On right bottom edge drop, top of case separated from laptop. No laptop damage noted.</p> <p>On top left edge drop, case slightly separated following drop. No damage to laptop noted</p> <p>On top right corner drop, minor scuffing was present on top right corner.</p> <p>Laptop did not appear to have any visible damage following drop testing. Minor scuffing was present on case. Device was fully operational at the conclusion of drop testing.</p>

Biasing / Monitoring:

The unit was in sleep mode during the test procedure. Following drop testing, device remained fully operational.

Test Equipment:			
Equipment Name	Model #	Serial #	Calibration Due

Drop Test Breakdown:

Angle	Pass	Fail	Notes
Front Face	X		
Back Face	X		
Top Face	X		
Bottom Face	X		Minor scuffing on bottom right corner
Right Face	X		Case separated on upper right corner
Left Face	X		
Top Right Edge	X		
Top Left Edge	X		Slight separation, no damage
Top Front Edge	X		
Top Back Edge	X		
Bottom Right Edge	X		Top of case separated from laptop. No damage to laptop.
Bottom Left Edge	X		
Bottom Front Edge	X		
Bottom Back Edge	X		
Right Front Edge	X		
Right Back Edge	X		
Left Front Edge	X		
Left Back Edge	X		
Top Right Front Corner	X		Minor scuffing
Top Right Back Corner	X		
Top Left Front Corner	X		
Top Left Back Corner	X		
Bottom Right Front Corner	X		
Bottom Right Back Corner	X		
Bottom Left Front Corner	X		
Bottom Left Back Corner	X		

Pictures



Pre-test photo of Top of Laptop



Pre-test photo of Bottom of Laptop



Minor scuffing on case



Case separation



Drop Test